

the method, all of the measurement values determined and stored in connection with step a) for all of the involved process colors are balanced with each other, such that for further color correction, a few or all of the process colors involved in the printing can be adjusted simultaneously.

Enclosed drawings

Number of enclosed drawings: 2